

#### **Cover Note:**

These slides were put together for a Northland Branch NZGS presentation on 02/06/2020. The information included in the slides does not standalone without some explanation. Please view the presentation recording on the NZGS website for the full context.

Sources of figures/pictures in the presentation are not fully acknowledged.

Historic aerial photos were sourced from <a href="http://retrolens.nz">http://retrolens.nz</a> and licensed by LINZ CC-BY 3.0.

A number of aerial photos and property boundaries were sourced from <a href="https://data.linz.govt.nz/">https://data.linz.govt.nz/</a> and licensed by LINZ CC-BY 4.0, typically Northland 0.4m Rural Aerial Photos (2014-2016) and NZ Parcel Boundaries Wireframe layers were used.

Geological maps where sourced from <a href="https://maps.gns.cri.nz/">https://maps.gns.cri.nz/</a> and licenced by GNS CC-BY.

Free software for stereo pair red/blue anaglyphs can be found here: <a href="http://stereo.jpn.org/eng/stphmkr/index.html">http://stereo.jpn.org/eng/stphmkr/index.html</a>

QGIS was used for terrain models and compiling figures/maps. This is open source and can be downloaded here:

https://qgis.org/en/site/forusers/download.html

A number of Google Earth images are used.

Borehole data has been obtained from the NZ Geotechnical Database for some of the sites: <a href="https://www.nzgd.org.nz/">https://www.nzgd.org.nz/</a>
Details of Landslip 2 were obtained from an Auckland Council Property File.

Hopefully you find the presentation useful.

**David Buxton** 

<u>David@northlandgeotech.co.nz</u>







Landslips in Northland Observations from Select Case Studies

David Buxton - Northland Geotechnical Specialists





## Landslip Sources

- Work history
- GNS database
- Geological maps
- Observations of road slips
- Review of aerial photos
- NZ Geotech database
- Discussions with others

The information discussed is public, although not always readily available. Traditionally individual landslips are not published and for most engineers there is no easy/accessible way to find out about many landslips. Hopefully this can change in the future.




### Disclaimer

- 1) This presentation is to learn from not to criticise.
- 2) I do provide my honest thoughts were I see due
- 3) Please don't take my honesty as individual criticism.
- 4) I'm also part of the learning.

There is time for questions following my presentation.



# My Personal Introduction








## Northland





### Northland





Map source:
NZ 8m DEM from LINZ
Qmap from GNS
Property Boundaries from LINZ
CC BY 4.0
Map generated in QGIS

Landslips 1 & 2 are in Auckland but relevant to Northland.




# Qmap - Kaitaia







# **Qmap** - Whangarei



#### Landslip 1 - My Professional Introduction





Figure 2. House site in Lingham Crescent, Torbay where a home damaged by slow movement (700 mm on 30 July 2008) of a creeping landslide was evacuated and later demolished. Site evidence suggests the landslide is an old feature that was active before the site was developed, and reactivated by the prolonged rainfall in July 2008.





[GNS Photo: GTH-0429].

Figure 4. View of house foundations (left) after the most severely damaged house in Lingham Crescent (above) was demolished. The concrete driveway seen here has slid 100 mm towards the road as a result of the landslide movement. [Photo S Nelis]

#### Engineers keep watch on North Shore slip

f 0 💆 0 🚜

News > National

A "creeping" landslip on Auckland's North Shore is under close scrutiny from engineers today as it threatens to take out more houses.

One house in the East Coast Bays suburb of Torbay has been written off and two others were damaged by the slip yesterday as ground sodden by days of heavy rain gave way.

The slip had been "slowly creeping" for several days, said North Shore City Council spokesman, Blair Harkness today.

Yesterday the ground in Lingham Cres gave way, leaving one house twisted on its cracked foundation and another two badly damaged.

As emergency services feared the slip could spread, 12 more houses were evacuated and it may be days before the residents were are allowed to return civil defence officers said.

An Earthquake Commission engineer was due back on the site today to assess the damage to the houses and the likelihood of further erosion of the slope.

The ground movement left a 12m split in the ground and residents were given a few minutes to gather important items and leave.

Everyone cooperated with civil defence officers to get out of their homes, David Keay, from North Shore City Civil Defence, said.




A large slip has caused the evacuation of more than a dozen homes on Auckland's North Shore



https://static.geonet.org.nz/info/reports/landslide/SR\_2009-004.pdf

Landslides caused by the June-August 2008 rainfall in Auckland & Wellington - GNS



The landslide that occurred in Lingham Crescent in Torbay was a deep-seated earth slide. Significant slide movements occurred on 30th July 2008 following a sustained period of heavy rainfall over two weeks. GNS Science staff (S Nelis and S McColl) inspected the site on 1st September 2008, after the most severely damaged house had been demolished and removed (Figure 2). The landslide is thought to be a reactivation of an older feature that was most likely active before the site was developed. Geomorphic evidence for this being a reactivated old landslide includes existing scarps 200-500 mm in height running through the back of the property (Figure 3).


(2) Although the recent landsides at Torbay, Glenfield, and Huia were clearly related to greater-than-normal rainfall, in these cases, however the underlying cause appears to have resulted from, or be associated with, development and building on old landslides (as at Torbay) or on previously unstable land that has undergone major alterations to the ground surface profiles, without due recognition or allowance for the underlying instability.

More reports at


https://www.geonet.org.nz/landslide/reports



Late to mid Pleistocene river and hillside deposits

























From a paper presented at the 2001 NZGS Conference....

#### Land Development Zones for Structure Plans

S. C. Tilsley

Beca Carter Hollings and Ferner Ltd

A. L. Williams

Beca Carter Hollings and Ferner Ltd

D. V. Toan

Beca Carter Hollings and Ferner Ltd

Hazard zoning was based on a 1:5,000 regional scale mapping and the project was for Auckland Council planning purposes.




Figure 1. Extracts from slope grade and lithologic map (A) and observed slope movements overlain on resultant slope instability hazard map (B).

Land may be unsuitable for development, severe limitations






#### **RE: SLIP REMEDIATION WORKS**

#### 41-49 CHAMBERLAIN ROAD, MASSEY

Soil Parameters

Soil Type	Effective Cohesion on the Failure Plane c' (kPa)	Effective Angle of Internal Friction Φ'(°)	Unit Weight γ (kN/m³)
Engineered Fill	7	28	18
Alluvial Deposits	2	26	18
Shear zone (rupture surface)	0	12	18








Photo 5 - Toe of slip in drain CD3 - up to 20mm displacement with the top layer overriding the base layer



Photo 8 - Up to 75mm of displacement observed on side of drain CD3







Table 7-2: Soil design parameter values

#	Weathered ECBF	Shear surface zone (at 13.5m depth)	ECBF rock
Unit Weight, (kN/m³)	18	18	22
Cohesion, c' (kPa)	5	5	10
Friction angle, $\varphi$ ' (°)	26	26	30
Anisotropic dip angle range (°)	N/A	2 to 12	N/A
Anisotropic cohesion, c' (kPa)	N/A	0	N/A
Anisotropic friction angle, $\varphi$ (°)	N/A	13	N/A -
Young Modulus, E (GPa)	20	20	150










Table 7-2: Soil design parameter values

# I	Weathered ECBF	Shear surface zone (at 13.5m depth)	ECBF rock
Unit Weight, (kN/m³)	18	18	22
Cohesion, c' (kPa)	5	S	10
Friction angle, φ' (°)	26	26	30
Anisotropic dip angle range (°)	N/A	2 to 12	N/A
Anisotropic cohesion, c' (kPa)	N/A	0	N/A
Anisotropic friction angle, $\varphi$ (°)	N/A	13	N/A -
Young Modulus, E (GPa)	20	20	150







# Don Buck Road, Massey – 2007 & 2015

From a paper presented at the 2001 NZGS Conference....

#### Land Development Zones for Structure Plans

S. C. Tilsley

Beca Carter Hollings and Ferner Ltd

A. L. Williams

Beca Carter Hollings and Ferner Ltd


D. V. Toan

Beca Carter Hollings and Ferner Ltd






## Northland







Movement in this area has been known since 1970's when the houses were developed and movement in the backyard of 4 adjacent properties occurred. One of the properties was recently again for sale, having again been purchased by an unsuspecting person. Could it have been identified in advance if it was a new development?






Method 1 – Geological Map – 1:25,000 Scale – Geology of the Whangarei Urban Area 2003 – Regional Geology









Geological Map – 1:25,000 Scale – Geology of the Whangarei Urban Area 2003 – Mapped Landslide






Use the LiDAR data – All of Northland imminent. Images below created in QGIS which is open source & free!






#### Whangarei: Some History









### Whangarei: Sudden Street Endings & Vacant Land a Warning?


















#### Whangarei: Sudden Street Endings & Vacant Land a Warning?



#### GEOLOGICAL HAZARDS

#### LANDSLIDES AND SLUMPING

the accompanying map by numbers in square brackets.

The large mass at Portland forms Tikorangi Hill which rises [14]. above the surrounding mudstones (Fig. 9).

In general, areas with a slope greater than 15° and underlain Allochthon (except Mahurangi limestone) are considered to much of the land south of Otaika Fault.

Several deep-seated, ancient, large landslides have been identified in areas underlain by Whangai Formation mudstone Deeper-seated gradual movement may occur on the thrust or Omahuta sandstone. Some have apparently not moved nature of the ground suggests relatively recent, large-scale undertaken down slope.

seems to be inactive [8].

Both old slope failures and recent movement affecting houses and streets are present to the north of the hospital on Maunu Te Kuiti Group rocks other than Ruatangata Sandstone (tr) Road [9], and sheet piling and rebuilding of the street was are generally not susceptible to landsliding. In places, necessary in Glendale Road [10]. These areas are also Ruatangata Sandstone stands in steep bluffs, but some minor underlain by Whangai mudstone, as are the large areas of landslides are present where it is weathered. It is very variable sliding near Colenso Street, Kamo [11], which show recent in strength


In many cases, it is apparent that vegetation has a significant effect on the shallow, creeping slides in Whangai mudstone Most natural slopes developed on soft rocks in the and Omahuta sandstone. Deforestation results in significant Whanearei area exhibit an undulating hummocky surface activation soon afterwards, but the level of activity in many that is characteristic of soil creep and surficial slumping (Fig. places has declined since the 1940s, probably as the slopes 18). Landslides in the map area have been mapped from have readjusted to a semi-stable lower angle under pasture aerial photographs and field mapping. The positions of than they had under forest. Any further modification of the features and landslides discussed below are indicated on landscape and drainage needs to make provision for possible


Whangai Formation mudstone (mw) is very susceptible to Areas of soft rock beneath hard, permeable units (e.g. basalt instability, even on gentle slopes of less than 10°, and in and limestone) are subject to both oversteepening of natural most cases the steeper slopes can be considered to consist slopes and saturation by groundwater, and are thus of a complex of creeping landslides, for example in the Otalka particularly unstable (Brown 1975). Such areas include most area [1]. These slides are probably in the order of 5 m deep, of the waterfront around Onerahi peninsula, where two but are possibly up to 20 m deep in places. The tendency of recently active areas are apparent - one adjacent to Johnson these rocks to slump arises from their generally clay-rich Street [12], and the other near the intersection of Hill Street composition and the intense tectonic shearing within them. and Church Street [13], at the east end of the airport runway. Instability is also widespread in areas of Omahuta sandstone Similar failures are present at the margins of the Tikipunga (00), particularly beside Limeburners Creek [2]. Mahurangi plateau and in parts of Maunu. West of Whangarei Hospital, limestone (om) is comparatively strong and areas of limestone large blocks of Whangarei Limestone are being rafted north are less prone to slumping and more resistant to erosion. down slope, by creep in underlying Ruatangata Sandstone

Three large, ancient slides between State Highway 1 and Vinegar Hill Road at the northern margin of the area mapped by Late Cretaceous and Tertiary soft rocks of the Northland [15, 16 and 17] are at least partially active, with large-scale, deep-seated creeping modes of failure. It appears that failure have a high risk of failure (Brown 1975). This includes parts of the underlying weak rocks has resulted in failure of the of Raumanga, Kioreroa, Morningside and Riverside, and edge of a basalt flow. The most easterly of these three slides [17], on the Mangakino Stream, contains large semi-intact

contact at the base of the Northland Allochthon where this for a long period, but others are obviously active, or at least dips in the same direction as the ground surface (e.g. partially active. A very large landslide at the Onerahi end of Raumunga, and beneath Whangarei Hospital [19]). Such Riverside Drive, north of Sherwood Rise [3], shows no signs movement may disrupt underground services and cause of recent activity, but a slide of similar size north of Otaika gradual displacement of building foundations, but is unlikely Creek [4] is probably creeping at present and the hummocky to have catastrophic effects unless major excavations are


The deeply weathered or hydrothermally altered zones in A failure of the old railway cutting in Whangai mudstone at Parahaki Rhyolite (cp) and Maungarei Dacite (km) are slightly Morningside [5] in the 1940s was subsequently stabilised susceptible to landsliding, but these are usually regolith by cutting back to 20°. Nearby, a large area of hummocky failures of no more than 2 m depth, incorporating topsoil and ground was formerly visible on the north-facing slope of weathered colluvium sliding on the clayey interface with the Morningside [6]; the area is now covered with houses. underlying weathered bedrock. Shallow regolith failures in Extensive ancient landslides on the west-facing slopes of pasture adjacent to Parakiore [20] cover a few hundred square Morningside [7] are also developed in sheared Whangai metres and are still active. Gully erosion is also a feature on mudstone, but have apparently been inactive for a long time. Parakiore, but the regeneration of scrub in this area in the The old slide in the area of the sewage treatment plant also last 30 years has inhibited further erosion. There are, however, two examples of large, ancient slides on the northwest slopes of Parahaki above Whareora Road [21].








### Northland



4 - Mangawhai





### 4 - Mangawhai




The LiDAR contours indicate a 9m fall over 45m horizontal distance between the headscarp and toe – an average of 1V:5H or 11°, indicating a very low strength failure plane must exist.






## Northland































Landslips in Northland. Observations from select case studies



# Northland






Awhitu Group Dunes

Early – Middle
Pleistocene
Estuary, river and
swamp deposits

Holocene River deposits



Undifferentiated Mangakahia Complex (Northland Allochthon)


Melange of Northland Allochthon

Mahurangi Limestone (Northland Allochthon)





#### New Zealand Geolechnical Dalabase







Northland Geotechnical Specialists

NZGD ID: BH\_116179



# TONKIN & TAYLOR LTD BOREHOLE LOG


BOREHOLE No: BH1


Hole Location: Concrete Driveway

SHEET 1 OF 5

PROJECT: EQC-Colville Road 52									LOCATION: 52 Colville Road, Dargaville JOB No: 25062										
CO-ORDINATES mN mE  R.L. m  DATUM										DRILL METHOD: OB/HQ Rotary  HOLE FINISHED BY: E									LE STARTED: 13/11/07 LE FINISHED: 13/11/07 ILLED BY: DCN Drilling Ltd GGED BY: CMW/RAM CHECKED:
GEOLOGICAL												E	ENC	SINE	ERI	NG	DESCRIPTION		
GEOLOGICAL UNIT, GENERIC NAME, ORIGIN, MINERAL COMPOSITION.				МЕТНОО	CASING			R.L. (m)	R.L. (m) DEРТН (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MOISTURE WEATHERING	STRENGTH/DENSITY CLASSIFICATION	25 SHEAR STRENGTH 50 (KPa)		20 STRENGTH 100 (MPa)	50 DEFECT SPACING		SOIL DESCRIPTION  Soil type, minor components, plasticity or particle size, colour.  ROCK DESCRIPTION  Substance: Rock type, particle size, colour, minor components.  Defects: Type, inclination, thickness, roughness, filling.
FILL OLD TOPSOIL ORGANIC FILL			80	OB						X X X X X X X X X X X X X X X X X X X	МН	М	S						CONCRETE, 100mm, non-reinforced Soft silty CLAY, some sand, some angular gravels, brown mottled yellow/light brown, moderate plasticity
			0	8	1.5m casing				0.5	X31 × 31 × 3× 1× 3× 1× 3× 1× 3× 1× 3× 1× 3× 1× 3× 1× 3× 1× 3× 1× 3× 3× 3× 3× 3× 3× 3× 3× 3× 3× 3× 3× 3×	МН	s w	VS						- wood fragments, very soft, dark brown, organic SILT, trace clay, no plasticity, trace 0.5 fine sand  - brown mottled light brown, clayey SILT, trace fine sand, trace organics, moderately plastic.
HIGH LEVEL COASTAL SANDS			06	OB					1.0-	× × ×									Very soft, sandy SILT, some clay (dilatent), slight plasticity, light whitish grey orange mottles












Open the Flood and Coastal Hazards (Natural Hazards) maps








 $13m \text{ rise over } 20m = 33^{\circ} (1V:1.5H)$ 




# Northland















Location of interest

Figure from "Out of the Ocean, into the Fire", Bruce W. Hayward, 2017





5.71 Geological map showing the surface distribution and structure of the Early Miocene Hokianga Basin rocks and their relationship to the underlying and sometimes overthrust Northland Allochthon rocks. A north-south cross-section of the inferred subsurface geology is shown (A-B). Modified from Hayward (1993) and Evans (1994).
























Landslips in Northland. Observations from select case studies








Northland



A 1:100,000 scale
Kaitaia-Whangaroa map
from DSIR 1989 is
available. It was
produced during efforts
to "unravel" the
Northland Allochthon. It
maps the Allochthon
and dunes as part of the
Motatau Complex






Undifferentiated
Pliestocene-Holocene
Landslide deposits


Hukerenui Mudstone

**Punakitere Sandstone** 



















TH.

#### 8 - Kaitaia

#### **TONKIN & TAYLOR LTD** BOREHOLE LOG

OREHOLE No: BH:	5
ole Location: Paddock- head	scarp
HEET 1 OF 3	

#### **TONKIN & TAYLOR LTD** BOREHOLE LOG

BOREHOLE No: BH5 Hole Location: Paddock- headscar **Geotechnical Specialists** 

PROJECT: G.									25.05								SHEET2 OF3
PROJECT: Geotech	mN	Inve	estig	gatio	on		_							Drive,	Kait	Series VI	JOB No: 17600.001
	mE											Tract					LE STARTED: 20/2/07 LE FINISHED: 21/2/07
R.L. DATUM	m											D: Ro	-				LE FINISHED: 21/2/07  LLED BY: Prodrill
GEOLOGICAL	$\top$	_				-		7.11	CO	LLAR	RL:	Water				LOC	GGED BY: DSBB CHECKED: C
GEOLOGICAL UNIT,			Γ				T	_	+	Г	g			ENGIN	EEF	RING	DESCRIPTION
GENERIC NAME, ORIGIN,										MBOL	WEATHERING		SHEAR STRENGTH	SIVE	CNIC		SOIL DESCRIPTION  Soil type, minor components, plasticity or particle size, colour.
MINERAL COMPOSITION.			VERY			TESTS	1		١	NO SY	WEAT	CTISNO NO	RP#)	COMPRESSIVE	DEFECT SPACING	(m)	
	SSO	_	CORE RECOVERY	Q.			83	1	GRAPHIC LOG	CLASSIFICATION SYMBO	NO.	STRENGTHIDENSITY	SHEA	STS	DEFE		ROCK DESCRIPTION  Substance: Rock type, particle size, colour, minor components.
	FLUID LOSS	WATER	SORE	МЕТНОВ	CASING		SAMPLES	R.L. (m)	RAPH	ASSII	MOISTURE	ASSIF				88	Defects: Type, inclination, thickness,
	1	-	77%	OB	1		00	e 2	×	ō	2 8	6 3	= NB ≥	888 <sup>§</sup>	R S	828	roughness, filing. occasional light brown mottles.
	11	1	7	100					×			1	Ш	ШШ	Ш		occasional right brown mothes.
									×					111111	Ш	Ш	
	11			-	1 65		II		- <u>×</u>				Ш	ШН	Ш		
	11	1	-	1					×				Ш	ШИ	Ш		
		1		- 1			H		* _ ×			9	Ш	ШШ	Ш	Ш	
	11	ŀ	+	-			П	6-	×				Ш		Ш		
							11		-×				Ш			Ш	
		1	%	բl					×_*				Ш		Ш	Ш	
	11	1	20%	HOH	1		П		-×			1	Ш	Ш	Ш	Ш	
				1			П		X	-			Ш			1	Pine SANDSTONE light grow warming
		-	4	_									MI.	Ш	Ш	b	Pine SANDSTONE, light grey, very weak and 80mm within highly sheared
		1						100	1		1	- 1	Ш	Ш	Ш	Hd	iltstone/mudstone, extremely weak, lisaggregates easily into fine gravel sized
	11		1	1	1			941	N /I				Ш	ШН	Ш	i i ib.	locks. IO RECOVERY. Lost core, re-drilled,
	11	1	1		1			7-	11/1				Ш	11111	Ш	l li	mited core recovered cuttings appear to be imilar to above.
		1						-	W				Ш	ШШ	Ш	1 31	illinar to above.
		1007	19%	3					1				IIII	ШШ	Ш	11	
		-	1	9				-	1	1	-		Ш		Ш	11	
						j		-	11			- 11	Ш		Ш	11	
	11		1						111				Ш		Ш	11	
					1	- 1		ī	/ V			- 11	Ш	WIII	Ш.	Ш	
3ox 2	11	L	1	4				8-	1			- 11	Ш	11111	Ш	11	
					1	- 1	-		1			- 11	Ш		Ш	No	O RECOVERY.
		ŀ		1	1	1		- 1	\ /			- 11	Ш			П	
						i		J	VI			- 11	Ш	11111	Ш	Н	
	Ш	%	HOTT		1	1			Y					ШШ	Ш		
			1	1				4	Λ				Ш	Ш	111		
į		1			1			J	$/ \parallel$	1		Ш	Ш	Ш	Ш		
							1	7	1								
		H	+	1		1	1	9	< x	-			Ш			STI	TSTONEAU IDSTONE SELL
							1	-	× × × × × × × × × × × × × × × × × × ×				Ш			In a	LTSTONE/MUDSTONE, highly sheared, a silt clay matrix, dark grey, light grey
							1	7	××				Ш	ШИ		mo	ottled, polished surfaces.
		%19	HOTT					4	×				Ш			1	
1		9	H					3	×	4			Ш			L	
1								1					Ш			cen	Omm thick highly fractured fine well mented SANDSTONE, grey.
1						1		- 3	×				Ш			As	at 9.0m, blocky sandstone inclusions.
								,	×				Ш				
DRTHLAND LLOCHTHON		%	L				1	10-3	*****							SIL	TSTONE/MUDSTONE, highly sheared, 10
		100%	HQTT					-X	×				Ш			in a	silt clay matrix, dark grey, light grey ttled, polished surfaces.
İ							1		×	-		111	Ш	Ш		1	
								10 ×		_		111	ш	1111111	111	-70.	mm thick blocky fine SANDSTONE,


PROJECT: Geotech	nical Inve	stiga	tion					LOC	ATIO	N: 94	Allen	Bell D	rive, Ka	itaia	JOB No: 17600,001			
CO-ORDINATES mN mE											Tractor			HOLE STARTED: 20/2/07 HOLE FINISHED: 21/2/07				
R.L.	m							DRI	LL ME	THOE	): Rota	ıry			ILLED BY: Prodrill			
DATUM		- 11						COI	LAR	RL:	Water		NONE		GGED BY: DSBB CHECKED: CM			
GEOLOGICAL	+		1					+		0		\$ T	NGINE		3 DESCRIPTION SOIL DESCRIPTION			
GEOLOGICAL UNIT, GENERIC NAME, ORIGIN, MINERAL, COMPOSITION.	FLUID LOSS WATER	CORE RECOVERY	МЕТНОО	CASING	TESTS	SAMPLES	R.L.(m)	DEPTH (m) GRAPHIC LOG	CLASSIFICATION SYMBOL	MOISTURE WEATHERING CONDITION	RENG	SHEAR STRENGTH	COMPRESSIVE STRENGTH	250 DEFECT SPACING 1000 (mm)	SOL DESCRIPTION Boll type, minor components, plasticity or particle size, colour.  ROCK DESCRIPTION Substance: Rock type, particle size, colour, minor components.  Defects: Type, inclination, bitkeness, roughness, filling.			
COLLUVIUM	1					1		7 <u>1</u> 1 <sup>N</sup>	OL	D	F	Ш	Ш	Ш	TOPSOIL, dark brown, organic, sandy silt.			
		70%	OB					2	МН	М	St				Clayey SILT, orange/brown, with organics, dark brown mottles.			
LANDSLIP DEBRIS		%09	OB	2/2007				x     x   x   x   x   x   x   x   x	МН	М	F/St				SILT CLAY, light brown orange, minor organics, moderately plastic, firm to stiff.			
		%001	SPT	1.5m on 20/02/2007	1 2						S				-light whitish grey with orange speckles, minor organics, soft.			
		100%	OB		2 N=4			2 -										
LANDSLIP DEBRIS Shear zone- 2.8m to 4.0m		100%	SPT		3 5			3 - 1 - 1 - 1 - 1			F/St				-becoming light grey with orange speckles, 20mm thick, clay gouge. -clay gouge 30mm thick, light grey, dark grey mottles. -disturbed sandy silt clay, with blocks of extremely weak sandstone, greyish orange mottles.			
HORTHLAND ALLOCHTHON					7 N=12			×			ExW				SILTSTONE/SANDSTONE, highly disturbed, blocky, disaggregates easily, grey, iron oxide staining, -light orange silt/clay mottles.			
		70%	OB					4	MF	I D	St/VS				SILT CLAY, grey, with siltstone/sandstone clasts, stiff to very stiff, some disturbance, occasional light brown mottles.			
NORTHLAND ALLOCHTHON D; BH 118312								5 - 2 - 3	MI	H D	St/VS				SILT CLAY, grey, with siltstone/sandstone clasts, stiff to very stiff, some disturbance, BORELOG TT 17600.001.GFJ 16			















# Northland






#### 9 - Coopers Beach



New Zealand Geolechnical Dalabase



Coopers Beach Landslip as suggested by T+T, review by GNS – report available.

#### 9 - Coopers Beach

Aerials Reviewed from:

1948

1970

1972

1976

1977


1981

1966 photos have good resolution but no overlap.

1948 Aerials provide the best viewing and are used for mapping of landslip scarp features.








#### 9 - Coopers Beach




#### Possible landslip scarp features to East of Coopers Beach







## Northland



#### 10 - Opua – Hihitahi Rise



# Slow-moving slip forces people out of Paihia homes

al Specialists

# Landslide and legal loophole strand families

Josh Fagan · 10:51, Feb 26 2015









Council: slip is private matter for insurers

05:00, Aug 07 2014







13 May, 2012 5:30am

① 7 minutes to read

Leonie Brittain, husband Chris and son, Ja Commission says they cannot build on. Ph

Herald on Sunday

#### As Is Where Is

A large four bedroom plus office home on a corner site in Te Haumi. Large family bathroom and master en-suite. Open plan kitchen and dining stepping down to a lower level lounge. Single garage.

The total home is in need of an internal and external make over. However, 230 square metres is a lot of home. There is a letter on file from the FNDC, which any intending purchaser should view, regarding the property. This is all reflected in the asking price.


#### **FEATURES**

Secure Parking

agura Darking

The subdivision where the Brittain family were to build their dream home is sliding down the hill, and nobody will accept responsibility. Their battle with bureaucracy reveals thousands of families could be equally vulnerable when they try to fulfil the Kiwi dream: building homes for their families. Susan Edmunds reports.

nzherald.co.nz/residential-property/news/article.cfm?c\_id=76&objectid=10805458



that cannot be economically stabilised by individual landowners.


The advice given to EQC in 2005 was to write all the properties off.

Rogers says the problem has the potential to grow larger.

A 50m borehole, properly logged, and with downhole defect orientation equipment, will be needed to get to the bottom of it, he says.

stuff.co.nz/auckland/local-news/northland/bay-chronicle/10354308/Council-slip-is-private-matter-for-insurers














As red-blue anagram




























#### **QGIS**
















#### **QGIS**









#### **QGIS**













Landslips in Northland. Observations from select case studies









Landslips in Northland. Observations from select case studies






Landslips in Northland. Observations from select case studies





Landslips in Northland. Observations from select case studies





# Stereo Pairs


- I hope that everyone looking at landslips has used a Stereoscope. Looking at aerial photos in 2D is not a suitable substitute.
- Credit to NRC for helping set up Retrolens and ensuring all the photos are available. I think we are still missing the WDC aerials from hazard zoning something to follow up.
- Once upon a time to look at smaller scale features you needed to order enlargements. Just getting copies of the photos could be hard/expensive. Photocopier enlargements were a cheap substitute and getting a pick of years was uncommon.
- We can view onscreen with freeware. You just need a pair of these







http://stereo.jpn.org/eng/stphmkr/index.html






Crop both pairs to the area of interest








#### Open pair:



Grey anaglyph




Open pair:





Put on glasses – use arrows to adjust image alignment to suit your eyes (adjustment often needed after zooming). You can pan and zoom with ease.







My recommendation – historic stereo pair photo viewing for all sites. It is free and available for all. Even with LiDAR DEM models it is still the best for a good portion of sites.



# **Hazard Zoning Comments**

- WDC hazard zoning is very good.
- It was completed from geomorphology with a detailed understanding of the geology.
- Quite a bit of time was spent in the field to validate the results.
- High risk Northland Allochthon is a different mechanism (usually) to high risk Greywacke – but don't ignore the high risk zoning.
- The mapping clearly follows geomorphic features (i.e. landslip scarps)
- Be very careful with less rigorous hazard mapping. Why:




# **Hazard Zoning Comments**

#### KDC hazard zoning:

Not clear how geomorphology is captured in the mapping other than a yes/no layer that doesn't appear to have a logical way of inter-relating to hazard zoning.

Slope stability hazard zoning by slope angle.




#### Geotechnical Assessment




Dargaville Kaipara District

Figure 4: Topographic Slope Angles



Northland Geotechnical Specialists

Figure 8: Slope Instability Potential




Geotechnical Assessment

Maungaturoto Kaipara District

Maungaturoto and surrounds was a high risk area with lots of actual landslips last time I drove through?? I see very little red and scarce orange, hmmm.



#### Lets check out Landslip 5:



Unfortunately not the excellence we saw with Landslip 2 Zoning

The KDC reports do have disclaimers but it does rely on the user to both read the report and be able to understand the disclaimers.

My personal view is that the public should be able to take such a report at face value without having to read in detail to identify the disclaimers

The reports (text) do in general identify the hazards.

In my opinion the slope angle thresholds are unconservative. They are of concern as others will it is likely they will be referenced and relied on in the future by some.

Based on slope angle alone the maps will always be insensitive to actual landslip features.




Table 2: Slope Instability Profile

Geologic Unit	Slope Instability Potential based on Slope Profile Ranges		
	Low	Medium	High
Tauranga Group Alluvium	<10°	10-23°	>23°
Kariotahi Group dunes	<14°	14-26°	>26°
Kerikeri Volcanic Group	<18°	18-45°	>45°
Taikura Subgroup	<18°	18-45°	>45°
Waitemata Group (includes Pakiri Formation and Ruarangi Formation)	<14°	14-26°	>26°
Northland Allochthon (includes Undifferentiated Mélange, Mahurangi Limestone, Whangai Formation)	<8°	8 18°	>18°
Whangarei Limestone	<8°	8-18°	>18°
Waipapa Group	<18°	18-45°	>45°

Landslip 4 in
Pakiri Formation
on 11° Slope!!!

Many Allochthon
Units are too
weak to stand
this steep



The slope profile ranges have been applied to the LiDAR contour and elevation data to generate the Slope Instability Potential plan presented in Figure 8. It is important to note that the "Low Instability Potential" category does not imply that instability will not occur on these slopes, particularly where underlain by Northland Allochthon strata. Rather, some of the slopes may have historically failed, which has resulted in the flatter slope angles observed today. Changes to the equilibrium of a slope through some combination of land modification earthworks, fill or building loading, or introduction of water, can trigger reactivation of previous landslides on any slope.



# Pictures of Northland Allochthon

For those who have not had the chance to dig and drill into it



Landslips in Northland. Observations from select case studies











Landslips in Northland. Observations from select case studies



Landslips in Northland. Observations from select case studies





Landslips in Northland. Observations from select case studies



Landslips in Northland. Observations from select case studies



Landslips in Northland. Observations from select case studies





Landslips in Northland. Observations from select case studies



# 10 Minute Challenge for any site?

- Google Earth
- Geological Map
- Google Street View
- DEM Terrain Model?
- Aerial photo review (maybe 30min)

Do this at the start so you know the range of possible issues, scope the site right, tell the client right from the start.


Our decision making is human – if we put ourselves in bad situations we make bad decisions.

Being "helpful" by ignoring the issues hurts our clients in the long term.



# Other References







## Conclusions

- Hopefully the presentation will aid your work.
- We need to identify and address the geomorphological features.
- Anyone signing a Geotech report in Northland needs to make sure they can identify the geomorphic features and ensure they have confidence in the staff who completed the onsite fieldwork.
- These are difficult sites. We should not rely on a single person's judgement. We should welcome peer review and will all benefit from it.
- Landslips happen remember the people. I have met many. Young families, elderly, people doing well, people with life struggles. Regardless, landslips take more than just a financial toll on these people.
- People trust us. We need to do a good job and be honest.
- Our understanding is always incomplete. There needs to be a level of robustness/margin for error in our work as we will usually be wrong to some extent.
- Being a Geotech in Northland does sometimes involve giving bad news a site not suitable to subdivide or a site not suitable to build on. We have to be prepared to have these discussions and reach these conclusions.



# Questions & Acknowledgements

